

Centrifuge Test Methods and Accessories

Items required for each test		ASTM D91	ASTM D96 (obs)	ASTM D893	ASTM D1796	ASTM D2273	ASTM D2709	ASTM D2711	ASTM D4007	ASTM D5546 (obs)
90040-0	Tube 8 inch x 100 ml cone-shaped (pack of 6)	•	•	•	•			•	•	•
90050-0	Tube 6 inch x 100 ml pear-shaped (pack of 6)						•			
90060-0	Tube 8 inch x 100 ml trace-sediment (pack of 6)					•	•			
90011-0	Tube 6 inch x 100 ml cone-shaped (pack of 6)		•							
90012-0	Centrifuge Tube 12.5 ml (pack of 6)		•							
90010-0	Setafuge Hazard Reduction System		•	•						
90001-2	Bucket Adaptor for 90040-0 & 90060-0 (pack of 4)	•	•	•	•	•	•	•	•	•
90002-0	Adaptor for 90012-0 Centrifuge Tube (Pack of 4)		•							
90003-2	Bucket Adaptor for 90050-0 (pack of 4)						•			
90041-2	Stoppers (pack of 50)	•	•	•	•	•	•	•	•	•
90202-3	5 Place Rack		•							
90203-2	6 Place Rack	•	•	•	•	•	•	•	•	
90204-2	4 Place Rack						•			
90200-5 or 90300-2 & 90301-2	Water Bath Seta Block Heater Block for Seta Block Heater	•	•	•	•	•	•	•	•	
90040-0	Tube 8 inch x 100 ml cone-shaped (pack of 6)	600-700 x g	500 x g	600-700 x g	500-800 x g			700 x g	600 x g	700 x g
90050-0	Tube 6 inch x 100 ml pear-shaped (pack of 6)						800 x g			
90006-0	Tube 8 inch x 100 ml trace-sediment (pack of 6)					600-700 x g	800 x g			
90011-0	Tube 6 inch x 100 ml cone-shaped (pack of 6)		500 x g							
Sample Pre-heat Temp.		32 to 35 °C	60 ±3 °C †	60 ±5 °C	49 ±1 °C or 60 ±1 °C	32 to 35 °C		82 ±1 °C	60 ±3 °C	25 ±1 °C
Test Temp.		Unheated	60 ±3 °C	Unheated	60 ±1 °C	Unheated	21 to 32 °C	60 ±1 °C	60 ±3 °C	Unheated
Test Time		10 mins	5 mins	20 mins	10 mins	10 mins	10 mins	10-15 mins	10 mins	10 mins

† Sample must be 52 °C or above after test